March 1998 - A sedge meadow located in the third quarter section from the north within the proposed wetland mitigation site at North Chicago.

September 2008 - Regulatory agency personnel, wetland scientists, civil engineers and transportation planners gather to evaluate the proposed wetland mitigation site at North Chicago.

NORTH CHICAGO WETLAND MITIGATION SITE

September 2008 - Wetland scientists from the Illinois Natural History Survey examine a degraded sedge meadow within the proposed wetland mitigation site at North Chicago.

January 2010 - A contractor walk through was conducted to identify the location of the state endangered shrub *Amelanchier sanguinea* prior to any work at the site.

NORTH CHICAGO WETLAND MITIGATION SITE

January 2010 - An Illinois Natural History Survey employee identifies the location of one of the state endangered *Amelanchier sanguinea* shrubs prior to any work at the site.

March 2010 - Hand clearing of undesired species is underway at the site.

NORTH CHICAGO WETLAND MITIGATION SITE

March 2010 - Pile of undesired brush and trees ready to be burned.

June 2010 - Selective clearing operations have moved into the south parcel.

July 2010 – Timber roadways are used to limit compaction in sensitive areas.

August 2010 – Clay tile being removed from the northern end of the site.